

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated: 27.06.2025

It is certified that the existing building ..... Gurukul International School (name of the building or premises) at (NH 52 Baramulla - Srinagar) Patanpur (Sikar) ..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground & 1st floor	2 NOS				

The building is owned/occupied by..... Gurukul International School ..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ..... P.W.D. .... (Name of Department/ Govt.) on..... 27.06.2025 (date of inspection) in the presence of ..... In. Arvind Kumar (AEN) ..... (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from..... 2009 ..... for a period of ..... 15 Years years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Dimension of room & building are not verified by P.W.D.
2. Only building of school is physical verified and
3. it found safe without any cracks in building.
4. Natural calamities are not part of this safety certificate.

Issued on 27.06.2025 at Patanpur by Arvind Kumar

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Arvind Kumar

Designation : Assistant Eng.

Name & Address of Department/ Office: P.W.D. Sub. Div. Patanpur, Sikar